


# XPLORE™

## Quick Reference for Forklift Solutions



### Example Solution:

1. xDock G2 Vehicle Dock
2. RAM adaptor plate for X-Dock
3. Double Socket Arm
4. D Ball Mount
5. KB Support Bracket w/ iKey KB - not shown
6. Lind 48V Power Adapter
7. xDIM (Dock interface module) - not shown

### Checklist of Components:

Secure Dock, VESA Mount, Arm, Forklift attach point, Power adapter and accessories

### Tablets: R12, F5m/C5m

#### Secure Docks

- 510.057.01 R12-Series Secure Mobile Dock
- 507.057.00 C5/F5-Series Mobile Dock w/ Key Lock

#### VESA Mounts

- 507.051.20 1.5" Ball Mount by RAM

#### Arm

- 507.051.21 1.5" Double Socket Arm by RAM (Long)
- 507.051.22 1.5" Double Socket Arm by RAM (Short)

#### Forklift Attach Point

- 507.051.23 1.25" Outer Diameter Pole Mount w/1.5" Ball by RAM
- 507.051.24 3" Clamp Width Base w/1.5" Ball by RAM

#### Power

- 601.530.05 48V DC Adapter by Lind

#### Accessories

- 508.551.01 USB Keyboard by iKey
- 510.057.03 R12 Keyboard Support Kit
- 601.825.07 Keyboard Support Bracket for Pole Mount



### Tablets: B10, D10, Bobcat, XC6

#### Secure Docks

- 02-05149 xDock G2 Vehicle Dock (BC,B10,D10,R)
- 02-05147-C xDIM G2 (BC,B10,D10,R)
- 02-05134-B Active xDim Pro (XC6)

#### VESA Mounts

- 507.051.20 1.5" Ball Mount by RAM

#### Arm

- 507.051.21 1.5" Double Socket Arm by RAM (Long)
- 507.051.22 1.5" Double Socket Arm by RAM (Short)
- 04-06016 Ram Arm 7-7/8"
- 04-06014 Ram Arm Base

#### Forklift Attach Point

- 507.051.23 1.25" Outer Diameter Pole Mount w/1.5" Ball by RAM
- 507.051.24 3" Clamp Width Base w/1.5" Ball by RAM
- 04-06040 Clamp Base Mount Kit

#### Power

- 601.530.05 48V DC Adapter by Lind
- 11-50037 DC to DC converter
- 55-02286 xDim G2 Wiring Kit

#### Accessories

- 55-02286 xDim G2 Wiring Kit
- 04-01032 Keyboard Tray. Tablets: (BC,B10,D10,R,C)

PLEASE NOTE: To ensure the most accurate installation configuration a vehicle audit is highly recommended prior to placing an order for vehicle mounts. Contact your Xplore sales representative or field engineer. Not all parts are in stock. Restocking fees (15%) will apply for incorrect self-configuration